

## Cultured Marble Top Bowing Tolerances

---

The final dimensions of a Showerama Cultured Marble top vary slightly from item to item due to the nature and behaviour of materials as well as the process of manufacture.

During the process of manufacture tops undergo extreme temperature variations, through the cooling process tops will shrink and distort which, in some instances, causes the top to bow.

For Showerama's standard of acceptable bow tolerances refer to Table 1.

TABLE 1  
Bow Limits for Showerama Cultured Marble Tops

Width/Depth	Bowing Tolerance (mm)
500	2
600	2
700	2
900	3
1200	4
1500	5
1800	6